

Knopke Brothers Contractors Supply 2-18-75
Mr. Jack Stapp-Service Manager 3:30 P.M.

A complaint was received at this office concerning a discharge of oil from Knopke Brothers Service Area. Contact was made with Mr. Jack Stapp, Service Manager. Mr Stapp was aware of the problem and was already taking steps to eliminate it. He explained to me that in the past, they had dumped their waste oil on the North edge of their property. After some time there was sufficient build up that whenever it rained the oil was being carried off. He said that he had not intended for this problem to get as bad as it did. He has ~~sense~~ put a stop to all dumping of oil in this area. Their waste oil is currently being put into 55 gallon drums. Also, there is a grate in the back of their service building that they have used in the past to do some degreasing over. This grate is tied to the Storm Sewer. He has also eliminated all such operations in this area.

Mr. Stapp expressed to me that as soon as the weather gets a little better, he would clean up the oil that was leaving the North edge of their property.

Mr. Stapp also expressed to me that he was beving a lot of trouble with his neighbor to the North, Mr. Stapp explained to me that his neighbor claims that when Knopke Brothers built their buildings in that area, it forced all the Storm runoff onto his property. Mr. Stapp also explained that this neighbor is blaming them for his basement flooding.

I told Mr. Stapp that I would check back with him, st a later date, to see that the improvements had been made.

Gene Pabst

Knopke Brothers Contractors Supply 4-12-75
1907 E. Bergman (Mr. Jack Stapp-Service Manager)

In following up a conversation with Mr. Stapp, on Feb. 18, 1975, an inspection of Knopke Bros. Property was made to see that the improvements , to stop the discharge of oil, have been made.

Mr. Stapp has cleaned up the area where oil was being dumped previously, He has also gravelled the whole area. Also, it appreas that all degreasing, over the storm grate, has been eliminated. Mr. Stapp has made all the improvements and the problem has been taken care of.

Eugene Pabst
Water Pollufion Control Inspector

1907 E. BERGMAN